

CASE HISTORY - Weatherford-ENI - Italy 925 Ball Valve



First Run cut top part of ball valve in 5 hrs
Motor Failed



Second Run cut bottom part of Ball Valve in 4 hours

