



## Case History Incoloy 925 Flapper

### Job Execution Well X-0X



- Used Contractor's flipping to lock out but flapper sided up.

Flipping Tool Photos



- Successfully milled out the flapper and regain access to the string.



Our 2.350" MX, Diamond-Impreg Mill was run for 10 hours milling to cut up the loose flapper. The mill produced no cuttings larger than particle size.  
Mill wear set. 15%

