



Case History BHI/Orca Frac Sleeve

Problem: Frac sleeves could not be milled out to size because sleeves would rotate.
Several WC mills were tried running high WOB with no result.

Our 4.552" to 4.652" SXR Diamond-Impreg Inserted/taper Reamer was run with very light WOB and very small back torque which cut 20" the first day and the rest of the 49" length the second day (working days).

