


Burning Over RDH Packer 6 3/4" x 5 7/8" XDS Shoe



Four Carbide Shoes made 3" and left carbide insert debris

One XDS Diamond-Impreg Shoe Cut through the carbide debris, the remaining upper carbide slips, the soft element, and into the bottom slip wickers to release the packer.

14 hours

6 hours

120 RPM
1-3,000 lbs WOB
1 Barrel/Min Fluid Circulation



Burning Over RDH Packer



**Burning Over RDH Packer
6 3/4" x 5 7/8" XDS Shoe**



Burning Over RDH Packer 6 3/4" x 5 7/8" XDS Shoe



New



Used (minus 10%)