



“Before and after burning over a 7” Hornet packer sitting at 60 degrees. The packer let go and started moving after 1-1/2 hours of drill time.”

Hornet Packer