


Case History: Burn Over Stuck 2 3/8" Cone Buster Mill & Loose Junk



Target: 2 3/8" Cone-Buster Mill Stuck with loose carbide packed into the annulus just above it.

2.375" X 1.700" XDS burn shoe cut the loose carbide and 3 1/2" of the carbide gage with no cuttings or junk left after the run.

Total run time = 13hrs.