



Case History  
4 5/8" SP-R  
Clean-Out Mill

Short Bit & Tool Co.  
225 Gold St  
Garland, Texas 75042  
972-205-1011



Stick Pipe reverse circulation 8,120 ft of abrasive fill and scale in 53 hours. In gage and refit with two new cutters.