
## CASE HISTORY - Weatherford-ENI - Italy 2.875" MX on 925 Ball Valve



First Run cut top part of ball valve in 5 hrs Motor Failed







Second Run cut bottom part of Ball Valve in 4 hours WOB = 1500 to 2500 lbs (385 to 641 psi)
Glossed Over



