

Case History

3.400" SBD-8 drilling SLB "Copper Head" Plugs Weatherford - Oman



First Run used on motor/CT to drill **five SLB aluminum "copperhead" plugs** and "some other target" .
Mill had fractured inserts in outer 1/2".

Mill was refit



Second job mill was used to drill five aluminum copperhead plugs in 10 hours and is good for reruns.

The SDB mill ran with light WOB and almost no stalls.

Case History

3.400" SBD-8 drilling SLB "Copper Head" Plugs Weatherford - Oman



Third Run

SDB milled 11 copperhead plugs in one run at about 75 minutes per plug

No used photo, but the report was that it was good for rerun.

Note: As of April 18, 2012 there are new mills on hand for another job.

Note: The SLB copperhead mill was run on the same application with negative results.