



Case History - Burn Over Diamond Mill

SUMMARY:

The target was a 2.550" matrix body diamond mill left down hole loose. Three carbide shoes showed no progress and left about 3" of loose carbide on top of the target. A 2.550" x 1.800" XDS diamond shoe burned through the loose debris and 2" of matrix and diamond gage to release the fish in 5 hours.



Short Bit & Tool Co.
225 Gold St
Garland, Texas 75042
www.shortbits.com