

Case History Hard Banded Drill Pipe



Many (estimated 12) carbide mills run to drill 120 feet of drill pipe with last piranha mill making NO new headway (stopped on tool joint).



3 7/8" MX-C was ordered/fabricated/and in the hole within 24 hrs and made a total of 190 feet to finish the job. As you can see the carbide inserts were not lost downhole even though they are completely shattered



Case History

Hard Banded Drill Pipe